Times are local to the site.

Fire Watch Shift Report

Shift overview	
Site: Harbor Point Sample Report Site	Provider: FireWatch Pros LLC
Specialist: Amy Nguyen	Outcome: Completed
Started At: Oct 7, 2026, 08:10:10.049	Ended At: Oct 7, 2026, 09:10:10.049
Elapsed shift duration: 1h 0m 0s	Incident Reported: Yes

Report: SHF000002 report 1
Shift: SHF000002

Jurisdiction Attestation

Jurisdiction: Downtown Tampa
Office: Tampa Fire Prevention Bureau
Phone: (813) 274-7000
Email: fireprevention@tampagov.net
Website: https://www.tampa.gov/fire-rescue

Ruleset Summary

Ruleset summary captured at shift completion.

Shift Summary

Specialist: Amy Nguyen
Outcome: Completed
Started At: Oct 7, 2026, 08:10:10.049
Ended At: Oct 7, 2026, 09:10:10.049
Recorded Tracking Start: Oct 7, 2026, 08:10:10.049
Recorded Tracking End: Oct 7, 2026, 09:10:10.049
Confirmed On-Site Seconds (Advisory): 0
Tracking Coverage: Incomplete recorded coverage
Incident Reported: Yes

Patrol Log

Due / completed	Result	Notes
Patrol 1 Due At: Oct 7, 2026, 09:10:10.049 Completed At: Oct 7, 2026, 08:35:10.049	All Clear: Yes Late: No	Fictional demonstration observation. Example post area reviewed; no actual field inspection is represented.

Evidence Manifest


Evidence 1



Category: general
Media type: image/png
Caption: Demonstration evidence: JUDGR sample image, not a field photograph.
Captured At: Oct 7, 2026, 08:35:10.049
Coordinates: 27.950600, -82.457200
Accuracy (m): 4.00
SHA-256: c94828c4856b262ee804321290cdfb054ad3ef64147b7c7d22d9f710e7c4a5ba

GPS Summary

Site Boundary: Not configured
Final Boundary State: not configured
Boundary Entries / Exits: 0 / 0
Boundary observations are operational evidence only.
Tracking evidence was frozen when the shift finished. Later corrections to shift times do not change the recorded route or boundary observations.



Sample Count: 2
First Sample At: Oct 7, 2026, 08:35:10.049
Last Sample At: Oct 7, 2026, 08:35:11.049
Duration (seconds): 1
Total Distance (m): 14.84
Average Accuracy (m): 4.50

Incident Summary

An incident was reported during this shift.

Verification

Report Template Version: Platform defaults
Branding Snapshot Source: provider_org_default
Verification Hash: a7b22d489279db3dd51aea4ad2303581906f4883c1eb5a4e38af4d5b26a8009f
Verification URL: http://127.0.0.1:28883/verify/01m4b7tgneg62eqaj1mx?hash=a7b22d489279db3dd51aea4ad2303581906f4883c1eb5a4e38af4d5b26a8009f

Evidence Manifest Count: 1